



Novartis Research Centre

Data and facts

Company	PORR Umwelttechnik GmbH in a consortium
Type	Demolition
Runtime	05.2013 - 10.2013
Principal	Sandoz GmbH

[Project report online](#)

www.porr-group.com



Rehabilitation, gutting and demolition

Gutting work was performed at the same time to remove all lines, cables and other infrastructure from the building. The buildings thus cleaned were then demolished. 124,000t of demolition material were treated and re-used at the construction site.

Impressions



Image notes

1

Novartis Research Centre.

The building, with all pollutants, lines and infrastructure removed, is being demolished.

2

Novartis Research Centre.

Demolishing the building complex

3

Novartis Research Centre.

Joint sealant is removed by means of high-pressure cleaner.

4

Novartis Research Centre.

Environmental protection by means of geotextiles

Do you have questions about the project or would you like to learn more? Feel free to contact us for further information.

PORR AG Group Communications

Absberggasse 47

1100 Wien

T +43 50 626-0

E-Mail: comms@porr-group.com